

# Oil Field Environmental Incident Summary

**Incident:** 20150216155930      **Date/Time of Notice:** 02/16/2015 15:59

**Responsible Party:** ONEOK Rockies Midstream

**Well Operator:** WHITING OIL AND GAS CORPORATION

**Well Name:** P WOOD 154-98-4-26-35 TIE In

**Field Name:** TRUAX

**Well File #:** 26488

**Date Incident:** 2/16/2015

**Time Incident:** 14:00

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 154

**Rng:** 98

**Sec:** 26

**Qtr:**

**Location Description:** South of HWY 1804 on county rd 15 approximately 1.5 miles and west approximately 1/2 mile.

**Submitted By:** Kim Rudningen

**Received By:**

**Contact Person:** Kimberly Rudningen  
2700 Lincoln Ave SE  
Sidney, MT 59270

**General Land Use:** Pasture

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Pipeline Leak

**Release Contained in Dike:** Yes - On Pipeline ROW

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	15	Gallons				

**Description of Other Released Contaminant:**

Natural gas condensates

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

There are no immediate risks associated with this release.

**Areal Extent:**

This release was contained within the bell hole on the pipeline ROW

**Potential Environmental Impacts:**

There are no expected environmental impacts due to this release.

**Action Taken or Planned:**

Work was immediately stopped in order to contain the leak. Impacted soils will be removed and disposed of.

**Wastes Disposal Location:** Recovered waste will be taken to a certified disposal landfill.

**Agencies Involved:****Updates**

---

**Date:** 2/16/2015    **Status:** Reviewed - No Action Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Small release in pipeline bell hole. Completely contained and impacted soils removed for disposal. No on-site inspection necessary.